



Catalog #: 1785-L60B

## PLC-5 Processor

Lifecycle status: DISCONTINUED

Rockwell Automation announces that as of December 31, 2015, the PLC-5 Processor will be discontinued and no longer available for sale. Customers are encouraged to remove references to the affected product(s).

**Discontinued Date:** December 31, 2015

**Replacement Category:** Engineering Replacement

## Technical Specifications

For full product specifications, please see the [product catalog](#).



Copyright ©2024 Rockwell Automation, Inc.